

NORTHERN DIVER

Cylinder Inspection and Test Certificate

Job No. 301369

Owner's Name Mr/Mrs/Ms _____ Forename/initials _____

Owner's Address TDG, HORSEA ISLAND, FDS,

Post Code PO6 4TT Phone No. _____

Make FABER Ser No 98/9743/091 Capacity 3 litre

A Periodic Inspection and Hydraulic Test or Visual Inspection only was carried out, in accordance with ASSET CP2 and BS EN 18119 or BS EN 1803 .

Comments

Visual: External condition: Satisfactory Fail

Visual: Internal condition: Satisfactory Fail

Make and identification of valve SOS 14-11/409

Valve maintenance in accordance with BS EN ISO 22434 and BS EN ISO 13341:

Physical condition: Satisfactory Fail

"DIN" outlet threads: N/A Satisfactory Fail

Valve stem threads: Satisfactory Fail

Cylinder neck threads: Satisfactory Fail

Valve: Replaced Y N Refurbished Y N

Eddy current test (Compulsory for AA6351/AA6082 Aluminium) Y N/A Pass Fail

Test unit: Visual Plus Visual Eddy Serial No _____

Note: When an eddy current test has been carried out, an additional mark or label is applied adjacent to the required test/inspection marks. This indicates to the filler that an eddy current test has been carried out.

Hydraulic test: N/A (Visual only) Pass Fail

This cylinder is is not fit for another period of use as defined by the above standards.

If passed, the next test/inspection is due on 01 / 12 / 23

Signed on behalf of the company S. Wall Date 24 / 06 / 21

Note: Cylinders and/or valves that fail the required inspection or test are retained for destruction as required by the applicable Standards.